



1 / 30




FIG. 1




FIG. 3




FIG. 2




FIG. 4

APR 28 2004

4 / 30




FIG. 5




FIG. 6




FIG. 8



900




FIG. 9



9 / 30

1000




FIG. 10

APR 28 2004

10 / 30




FIG. 11

O I P E
APR 28 2004
U.S. PATENT & TRADEMARK OFFICE

11 / 30

1200




FIG. 12



12 / 30




FIG. 13

13 / 30




FIG. 14A




FIG. 14B




FIG. 14C



14 / 30





FIG. 15



15 / 30



16 / 30




FIG. 17




FIG. 18




FIG. 19



19 / 30




FIG. 20



20 / 30

2100






FIG. 21



A1	A0	C0	C1	C2	C3	2220
0	0	1	0	0	0	$C0 = \overline{A1} \cdot \overline{A0}$
0	1	0	1	0	0	$C1 = \overline{A1} \cdot A0$
1	0	0	0	1	0	$C2 = A1 \cdot \overline{A0}$
1	1	0	0	0	1	$C3 = A1 \cdot A0$



2240	A1	A0	C0	C1	C2	C3	2252
$C0 = \overline{A1} \cdot \overline{A0}$	0	0	1	1	0	0	2252
$C1 = \overline{A1} \cdot \overline{A0}$	0	1	0	0	0	0	2254
$C2 = A1 \cdot \overline{A0}$	1	0	0	0	1	1	2256
$C3 = A1 \cdot \overline{A0}$	1	1	0	0	0	0	2258

FIG. 22




FIG. 23



23 / 30




FIG. 24



24 / 30

2500




FIG. 25



25 / 30

2600




FIG. 26




FIG. 28





FIG. 29




FIG. 30



30 / 30

3100




FIG. 31